




# RAHUL ENGINEERS LABORATORY

(A Govt. of INDIA Regd. MSME Unit)

ISO 9001:2015 Certified & ISO/IEC 17025:2017 Accredited Laboratory  
By NABL (Quality Council of India)

Udhyan (MSME) - UDYAM-RJ-33-0016428  
GSTIN - 08ACZPP5856A2Z0  
PAN - ACZPP5856A



FACILITIES : Testing of Cement, Aggregate, Bricks, Concrete, TMT Steel Bar, Paver Block, Bituminous Mix, Soil, Sand, Rock, Water, Ores & Minerals, Quartz, Feldspar, Soapstone, Diatomaceous / Siliceous Earth, Lime Stone, Dolomite, China Clay, Iron Ore & Bauxite

5-A, Chitrakut Nagar, Bhuwana By-pass Road, Udaipur (Raj.) PIN 313 001, INDIA

☎ : +91 6350324167, +91 8107343935, ✉ : lab@rahulengineers.com, rahul.labudr@gmail.com, 🌐 : www.rahulengineers.com

Doc.No.-REL/7.8/Chem./TR/F-2/REV.00 Dated. 01.01.2020

Report No: - REL-Chem. /230049-2

Date: -14.04.2023

ULR No-TC795423000000439F

## TEST REPORT (Dolomite Powder)

1	Name of Customer	:	<b>Ved Enterprise Opp High School, Bh Mahadev Mandir, Vasad, Anand, Gujarat, 388306</b>
2	Customer Contact No.	:	9909011488 , (vedenterprise.vasad@gmail.com)
3	Customer Reference No.	:	Service Request Form, Date: 11.04.23
4	Type of Sample	:	Dolomite Powder
5	Sample Identification	:	Mark- B (C)
6	Date & Mode of Receipt of Sample	:	11.04.23, Sample submitted by customer.
7	REL Job No	:	REL-230049-2
8	Name of work	:	Testing of Dolomite Powder Sample.
9	Location	:	.....
10	Date of Sampling	:	.....
11	Date of Testing	:	12.04.23 to 13.04.23

### Test Results:-

S. No.	Parameters	Test Results	Test Method Reference	Remarks
1	MgO (%)	20.90	IS 1760 (Part-3):1991 (RA-2017)	.....
2	Silicon as Si (%)	1.96	IS 1760 (Part-2):1991 (RA-2017)	

Tested By:

(R.N. Dixit)  
Chemist

Authorised By:

(S. Parikh)  
Tech. Manager (Chem.)

Note: - 1. Test report is authentic only if contain hallmark and seal.

2. The test results refer only to the samples received in the Laboratory.

3. Rahul Engineers Laboratory shall not in any way be involved in any action following the interpretation of test results.

4. Any discrepancy in test results should be reported within 15 days.

5. This report shall not be reproduced except in full without written approval from Rahul Engineers Laboratory.

6. Subject to Udaipur Jurisdiction only.

End of Report